US ERA ARCHIVE DOCUMENT

H	ľ
	ŀ
_	ŀ
ш	ŀ
_	
2	
5	ŀ
_	
u	ľ
\boldsymbol{a}	ļ
O	
Ω	
ш	
5	
>	
-	
-	
O	
\sim	
•	
A R	
⋖	
Δ	
ш	
S	
=	
_	
	L

A Link Name/Designators	1. Incident Name		2. Date Pr	repared	3. Time Prepared		UNIT LOG	
Name	Kalamazoo River/Enbridge Spill				ICS 214			
Name	4. Unit Name/Design	<u>nators</u>		5. Unit Le	eader		6. Operational Per	iod:
Position: Operations Section Chief To: 17:00	Operations Unit/Containment Branch Monitoring		Name:			From:		
Dan Capone			Position:	Operation	ns Section Chief	То:		
Dan Capone Operations Section Chief Operations Section Chief								
Deputy Director		Name		ICS Position		DUTY CELL		
Rex Johnson	Dan Capone	-		Operations Section Chief				
Dan Zahner	Joe Victory			Operations	Section C	hief		
Monitoring Group Supervisor CBM Team # 1 CBM Team Team Total Collection Points CBM Team Team Total Boom Deployed CBM Team Activity: CBM Team Team Team Team Team Team Team Team	Rex Johnson			Deputy Dia	rector			
CBM Team #1	Dan Zahner			Field Team	n Lead			
Activity Area EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN	Karen Berecz			Monitoring	g Group Su	pervisor		
Activity Area EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN	Joseph Kendall			CBM Tear	n #1			
Activity Area EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN DENSITY OIL /SHEEN DE				8. A	ctivity Log			
Activity Area EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN DENSITY OIL /SHEEN DE								
DIL OBSERVED DENSITY OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN							LAT	LAT
DIL OBSERVED EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN	Activity Area							
DENSITY OF OIL /SHEEN							(DD.MMMM)	(DD.MMMM)
Points Total Boom Deployed	OIL OBSERVED				L .			
Deployed								
Deployed								
Weston/START Containment Branch Monitoring Group (CBM) Team Activity: Joseph Kendall and David Pesses conducted (1) Control & Containment Point inspections at shoreline locations at Talmadge Creek. (2) Control & Containment Point inspections at shoreline and overbank locations from Kalamazoo River mile point 0.00 through 40.00. (3) Water & Sediment Temperature & Level Readings. • 0630: Meeting with EPA, START, and Enbridge contractors to discuss Containment Operations. • 0730 - 1700: START and NRG members conducted inspections. Observations and recommended actions were logged in the START CBM Team 1 log book, as well as discussed with David Pesses. David Pesses informed Enbridge contractors to make recommended actions. Activity								
Joseph Kendall and David Pesses conducted (1) Control & Containment Point inspections at shoreline locations at Talmadge Creek. (2) Control & Containment Point inspections at shoreline and overbank locations from Kalamazoo River mile point 0.00 through 40.00. (3) Water & Sediment Temperature & Level Readings. • 0630: Meeting with EPA, START, and Enbridge contractors to discuss Containment Operations. • 0730 - 1700: START and NRG members conducted inspections. Observations and recommended actions were logged in the START CBM Team 1 log book, as well as discussed with David Pesses. David Pesses informed Enbridge contractors to make recommended actions. **Activity** **WATER** SEDIMENT** WATER** ICE** ICE** ICE** ICE** **LOCATION** TEMP** TEMP** LEVEL** THICKNESS** FORMATION** FRAZZLE** **MP 2.25 C 0.0**	200300	Weston/START	Contain	ment Bran	ch Monit	oring Group (CI	BM) Team Activity:	,
LOCATION TEMP LEVEL THICKNESS FORMATION FRAZZLE MP 2.25 C 0.0 - - - - MP 5.25 C 0.4 - - - - MP 10.00 C 3.2 - - - - MP 15.00 C 5 56.0 53.0 3.6 - - - MP 15.6 Culverts N/A N/A N/A - - - MP 18.75 D 2 52.5 54.9 2.0 - - - MP 21.50 D 5 52.4 52.2 5.9 - - - MP 27.00 E 0.5 53.9 52.7 2.45 - - - MP 30.00 E 2 54.2 51.9 1.1 - - - MP 35.00 E 3 57.1 52.5 0.8 - - -		Joseph Kendall and David Pesses conducted (1) Control & Containment Point inspections at shoreline locations at Talmadge Creek. (2) Control & Containment Point inspections at shoreline and overbank locations from Kalamazoo River mile point 0.00 through 40.00. (3) Water & Sediment Temperature & Level Readings. • 0630: Meeting with EPA, START, and Enbridge contractors to discuss Containment Operations. • 0730 - 1700: START and NRG members conducted inspections. Observations and recommended actions were logged in the START CBM Team 1 log book, as well as discussed with David Pesses. David						
MP 5.25 C 0.4 MP 10.00 C 3.2 MP 15.00 C 5 56.0 53.0 3.6 MP 15.6 Culverts N/A N/A N/A N/A MP 18.75 D 2 52.5 54.9 2.0 MP 21.50 D 5 52.4 52.2 5.9 MP 27.00 E 0.5 53.9 52.7 2.45 MP 30.00 E 2 54.2 51.9 1.1 MP 35.00 E 3 57.1 52.5 0.8	Activity							
MP 35.00 E 3 57.1 52.5 0.8		MP 5.25 C 0.4 MP 10.00 C 3.2 MP 15.00 C 5 MP 15.6 Culverts MP 18.75 D 2 MP 21.50 D 5 MP 27.00 E 0.5	N/A 52.5 52.4 53.9	N/A 54.9 52.2 52.7	N 2. 5. 2.	/A - .0 - .9 - 45 -	- - - - - -	- - - - - -
							-	-
							- -	-

	AFTER RAIN EVENT INSPECTION: Not Completed Today.
	Talmadge Creek: (11) Pom-Poms deployed at:
	MP 0.0: Intact and looks good. MP 0.04: Intact and looks good. MP 0.27: Intact and looks good. MP 0.50: Intact and looks good. MP 0.74: Hillbilly Road: Should be replaced, thin film of Black Algae. MP 1.09: Intact and looks good. MP 1.28: Intact and looks good. MP 1.57: Intact and looks good. MP 1.77: Intact and looks good. MP 1.99: Intact and looks good. MP 1.99: Intact and looks good. MP 2.25: Intact and looks good.
	STANDARD DAILY INSPECTIONS:
	Talmadge Creek: (1) Control Point (CT) deployed at:
	MP2.25 Confluence: SWAT onsite Removing all All Hard-Boom's.
	Kalamazoo River: Control (CT) & Containment (CTM) Points (10) deployed are:
	MP10.75 L2 SO CTM Area of Sheen is 0' x 0' = 0 sq. ft. MP11.75 L2 (11.79 LDB) CTM Area of Sheen is 0' x 0' = 0 sq. ft. MP15.00 I1 (14.98 I) CTM Area of Sheen is 0' x 0' = 0 sq. ft. MP15.65 (Waterfall) CT Area of Sheen is 0' x 0' = 0 sq. ft. MP17.00 L1 (Rock Tenn) CTM Area of Sheen is 0' x 0' = 0 sq. ft. MP21.50 R1 CTM No Visible Sheen. Hard-Boom Looks Good. Area of Sheen is 0' x 0' = 0 sq. ft. MP37.75 (E-4): CT Area of Sheen is 0' x 0' = 0 sq. ft.
	ADDITIONAL AREAS OF CORCERN:
	Helicopter Fly-Over Pictures: Sheen Locations:
	MP 15.00 LDB: Visible Organic Sheen Only. Someone started digging a trench from pooling water wetland area and trying to drain off to river.
	Total sheen in control points: 0 sq. ft. Total sheen within containment: 0 sq. ft. Total Sheen: 0 sq. ft.
Health and Safety Issues	NONE
Comments	NONE
•	